




- ✓ Cuts through grease and burnt on food
- ✓ Powerful alkaline formula



**Always Wear
Correct PPE
Check Safety
Data Sheet**

Hazardous Pictograms



Ensure surfaces are cold. Remove any loose food deposits



Apply on surfaces to be cleaned and leave to work for 5 minutes



Wipe off with a cloth or abrasive pad, rinsing frequently to prevent clogging



Repeat for heavy soiling or if the oven has not been cleaned for some time



Not suitable for use on copper, brass or aluminium or its alloys



Empty – Rinse – Recycle

