



- ✓ Fast acting
- ✓ Safe on stainless steel
- ✓ Taint free




**Always Wear
Correct PPE
Check Safety
Data Sheet**


Hazardous Pictograms




Place appropriate
cleaning signs



Pour 150mls of C18
into the machine




Then add 600ml of
fresh water




Switch the machine
on and run for a few
seconds to prime



Leave for 1 hour and
then run through
the remainder of
the solution



Rinse thoroughly
three times with
fresh water



Empty – Rinse –
Recycle